

Product Description	A classic Polyurethane and Thixotropic alkyd based Low Gloss Enamel , which has been especially formulated to give the best of long term performance/durability, Water and Steam resistance with no mess, non drip application properties it can used for coating a wide range of prepared house hold surfaces such as doors, window frames, cup boards etc in kitchens, Bathrooms and other high traffic areas	
Application Areas	<ul style="list-style-type: none"> • Hardboard and fibre cement boards. • Primed metal and wooden substrates. 	
Product Features	<ul style="list-style-type: none"> • A high abrasion resistance, Low Gloss Durable Finish mostly for Interior use • Excellent adhesion and hiding power. • Excellent water and steam resistance due to the presence of the Polyurethane • Excellent, no mess non drip application properties. • Can be cleaned with normal house hold cleaners on a regular basis. 	
Product Data	Resin Base	Synthetic Alkyd resin
	Drying Time	Touch dry: 4-6 hours Hard dry: 16-18hours
	Film Thickness	± 30 microns
	Spreading Rate	8-10 SQM per 1 litre Although the spreading rate will vary with porosity and type of substrate, for uncoated new surfaces work on 7-9 square metres per litre for the first coat and 9-11square metres per litre for subsequent coats and for when applied to sealed, previously painted substrates.
	Surface Appearance	Low velvet like Gloss
Application Details		
• Mixing	Always stir well before use with a flat paddle.	
• Application Method	<ul style="list-style-type: none"> • Brush, roller or spray application. 	
• Thinning	This is ready for use un-thinned; thinning with White Spirits will reduce its hiding power.	
• Cleaning	Application equipment clean up is with White Spirits	
• Application	<ul style="list-style-type: none"> • With brush, roller or spray, apply a generous coat of Paint Master High Gloss Enamel to the area that needs protecting. • Allow to dry overnight before recoating. • Application equipment clean up is with White Spirits. • Do not apply before 09:00 and after 16:00 in the winter. 	
Surface Preparation		
• Rusted Metal	<ul style="list-style-type: none"> • Remove any rust and mill scale from steel surface. • Affected areas need to be cleaned back to bright metal • Apply one coat of Solvent or Water Based Metal Red Oxide , leave to dry over and apply a coat of Paint Master Universal Undercoat, allow to dry over night lightly sand, wash off sand allow to dry . • Apply two coats of Paint Master Non Drip Enamel. 	
• New Metal	<ul style="list-style-type: none"> • Degrease surfaces with an abrasive Degreaser to remove the manufacturer's grease protective layer. This process is repeated until the surface is water break free. • After drying Apply one coat of Solvent or Water Based Metal Red Oxide , leave to dry over and apply a coat of Paint Master Universal Undercoat, allow to dry over night lightly sand, wash off sand allow to dry . • Apply two coats of Paint Master Non Drip Enamel 	
• Dry, Uncoated Concrete Surfaces	<ul style="list-style-type: none"> • Make sure concrete is firm and completely dry. • Remove all dust, foreign material, fungal, algae growth. • Fill all visible cracks with a suitable Crack Filler and allow to dry • Seal repaired areas with Paint Master WB or SB Plaster Primer. • Apply one coat of Paint Master WB or SB Plaster Primer • Apply two coats of Paint Master Non Drip Enamel 	
• Fibre Cement Surfaces (Uncoated, Weathered or New)	<ul style="list-style-type: none"> • Remove dust, foreign material, fungal and algae growth. • If friable or powdery, seal with Paint Master Bonding Liquid. • Apply a Coat of Paint Master WB or SB Plaster Primer • Apply 2 Coats of Paint Master Non Drip Enamel. 	

<ul style="list-style-type: none"> • Raw Plaster 	<ul style="list-style-type: none"> • Make sure plaster is firm and completely dry. • Remove all dust, foreign material, fungal and algae growth. • Fill and seal all visible cracks and prime with Paint Master WB or SB Plaster Primer • Apply two coats of Paint Master Non Drip Enamel
<ul style="list-style-type: none"> • Previously Painted Surfaces 	<ul style="list-style-type: none"> • Make sure old paint coatings are firm and solid. • Remove all loose, flaking and bubbling paint. • Remove all dust, grease, foreign material, fungal and algae growth. • If powdery or friable, seal with Paint Master Bonding Liquid. • Prime with Paint Master WB or SB Plaster Primer. • Apply two coats of Paint Master Non Drip Enamel.
<ul style="list-style-type: none"> • Wood and Wood Fibre Boards 	<ul style="list-style-type: none"> • Sand surface until smooth. • Apply one coat of Paint Master Universal Undercoat. • Apply two coats of Paint Master Non Drip Enamel.
Colour Range and Quantities	<ul style="list-style-type: none"> • A wide range of Colours from The Paint Master Tinting system • Available in 1 litre, 5 litres and 20 Litres.
Precautions	<ul style="list-style-type: none"> • This product is flammable. • Use only in well ventilated areas. • Do not eat, drink or smoke while applying. • This product contains no toxic substances.
Disclaimer	<p>Martin Vosloo Paints can not be held liable if the product fails due to improper surface preparation or application.</p>
Martin Vosloo Paints	
<p>011-7083166/083-2671122</p>	<p>martinvosloo@mweb.co.za</p>